



GERENCIA TECNICA
AREA DE MANTENIMIENTO

ANEXO 2

DESATORO DE BUZONES, REDES y CAJA DE REGISTRO DE ALCANTARILLADO SANITARIO

AÑO : 2009
MES : NOVIEMBRE

DIA	RED						BUZON						CAJA REGISTRO						
	HUANCAYO		EL TAMBO		CHILCA		HUANCAYO		EL TAMBO		CHILCA		HUANCAYO		EL TAMBO		CHILCA		
	D	E	D	E	D	E	D	E	D	E	D	E	D	E	D	E	D	E	
1																			
2					1						4		1						
3	1												2		1				
4	3				3						1		1		2		1		
5			1		1		2								1				
6	1														1				
7																			
8																			
9			2						1				2		1		1		
10	1						1						1		2		2		
11	1				1		1		1				1		2				
12					1				1				1				1		
13																			
14																			
15																			
16	1		2		2				1				3		4		1		
17	2		4				1				1		3	2	2	1		1	
18	1				1		1				1		1	2					
19	2		1		2		3						3		1	2			
20	1		1		1				1				1				1		
21	2									2	1			1		1	3	2	
22									1				3		1				
23	1		3		3		1		1				7	3	6		2		
24	1				2		5						3	4					
25	5	1	1		2		3		2		1		3	1		2	2		
26	4		1				2	4			1		2	1					
27	2		1		2		1	4	1	1			1		1		2		
28	2							1		1			1		2	2			
29									1				1						1
30	1		4	2			2		1				2	4	5	3	3		
SUB TOTAL	32	21	21	2	22	0	17	15	9	7	10	0	39	22	31	12	19	4	
TOTAL	53		23		22		32		16		10		61		43		23		
EJECUTADO			98						58						127				